

FIG. 1





FIG. 2

FIG. 3




FIG. 4




FIG. 5






FIG. 6**FIG. 7**

FIG. 8





FIG. 9



00628026-072800

FIG. 10




FIG. 11

WARNING

IT IS PROHIBITED BY LAW TO COPY
IMAGE WHICH IS BEING READ.

READING OPERATION IS INTERRUPTED.

FIG. 13

WARNING

IT IS PROHIBITED BY LAW TO OUTPUT
IMAGE WHICH IS BEING PRINTED.

PRINTING OPERATION IS INTERRUPTED.

FIG. 12




FIG. 14




FIG. 15

SCANNER	SPECIFIC IMAGE 1	JAPANESE YEN BANK BILL
	SPECIFIC IMAGE 2	AMERICAN DOLLAR BANK BILL
PRINTER	SPECIFIC IMAGE 3	DEUTSCH MARK BANK BILL
	SPECIFIC IMAGE 4	BRITISH POUND BANK BILL


FIG. 17

FIG. 16




FIG. 18




FIG. 19




FIG. 20A





FIG. 20B

FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25A





FIG. 25B

FIG. 26




FIG. 27




FIG. 28

